



## Temperature

**Setting temperature range** without light, with humidity: +5 to +70 °C

---

**Setting temperature range** without light, without humidity: 0 to +70 °C

---

**Working temperature range** without light, with humidity: +5 (at least 20 below ambient temperature) to +70 °C

---

**Working temperature range** without light, without humidity: 0 (at least 20 below ambient temperature) to +70 °C

---

## Humidity

**Setting range humidity** 10 - 90 % rh

---

## Control technology

**Function HeatBALANCE** adapting the distribution of the heating performance of the upper and lower heating circuit from -50 % to +50 %

---

## Standard equipment

**Works calibration certificate** for +25 °C/40 % rh and +40 °C/75 % rh

---

**Door** fully insulated stainless steel doors with 2-point locking (compression door lock)

---

## Textured stainless steel casing

**Installation** on lockable castors

---

## Electrical data

**Voltage** 115 V, 50/60 Hz

**Electrical load** approx. 1600 W

---

## Packing/shipping data

**Dimensions approx incl. carton** w x h x d: 1370 x 1970 x 1300 mm

---

**Gross weight carton** approx. 424 kg

---

**Standard units are safety-approved and bear the test marks**

